

# ATMPartMart.com

Your ATM Headquarters




Flat Rate Repair Pricing - No Charge for non-repairable items.



\* All part repairs come with our industry-leading 7 month warranty! \*

\*\* Clicking on the repair item will take you to the item on our website for ordering \*\*


Contact us with any questions: (866) 417-2286

**Repair items in RED indicate a temporary special. Don't miss out!**

Manufacturer	Category	Product Model	Product Name	Price	
	Cassettes	R09005-00004	Repair of Talaris / DeLaRue SDD Cassette, Includes Metal Rails	\$104.00	
		Dispensers (CDU)	R09005-00082	Repair of Talaris / DeLaRue MiniMech Dispenser	\$188.00
	R09005-00202		Repair of Talaris / DeLaRue NMD100 Dispenser	\$472.00	
	R09005-00090		Repair of Talaris / DeLaRue NMD50 Dispenser, Two High	\$367.00	
	R09005-00038		Repair of Talaris / DeLaRue SDD1700 Dispenser	\$251.00	
	Mainboard & Electronics	R04005-00165	Repair of Talaris / DeLaRue NMD Central Machine Controller NMD 50	\$314.00	
		R04005-00062	Repair of Talaris / DeLaRue NMD Central Machine Controller, CMC 100/101	\$314.00	
		R04005-00034	Repair of Talaris / DeLaRue NMD Note Feeder Controller Board, NFC 100/101	\$314.00	
		R04005-00064	Repair of Talaris / DeLaRue NMD Stacker Presenter Controller Board, SPC 101	\$209.00	
		R08010-00035	Repair of Talaris / DeLaRue SDD 1700 Dispenser Board, If Sent Separately	\$157.00	
	Power Supplies	R04005-00060	Repair of Talaris / DeLaRue NMD 100 Power Supply	\$146.00	
		R09110-00129	Repair of Triton 9100 Power Supply For MiniMech	\$136.00	
		Card Readers	R06100-00139	Repair of Hyosung Card Reader	\$79.00
			R24118002-1	Repair of Hantle / Tranax Card Reader	\$79.00
		Cassettes	R14111309-1	Repair of Hyosung / Tranax 1,000 Note Cassette & Note Separator Unit	\$188.00
R41111310-1			Repair of Hyosung / Tranax 2,000 Note Cassette & Note Separator Unit	\$188.00	
R7900000794			Repair of Hyosung / Tranax Cassette Note Separator Unit	\$185.00	
R15111339-4			Repair of Hantle / Tranax MCDU Cassette	\$146.00	
R14116100-1			Repair of Hantle / Tranax SCDU Cassette	\$146.00	
Dispensers (CDU)	R728413-01	Repair of Hyosung / Tranax 1,000 Note Dispenser	\$251.00		
	R728413-00	Repair of Hyosung / Tranax 1,000 Note Drawer Dispenser	\$262.00		
	R728413-02	Repair of Hyosung / Tranax 2,000 Note Dispenser, New Belts If Needed	\$262.00		
	R728413-04	Repair of Hyosung / Tranax 4,000 Note Dispenser, New Belts If Needed	\$356.00		
	R728413-06	Repair of Hyosung / Tranax 6K - 8K Note Dispenser, New Belts if Needed	\$461.00		
	R72840620	Repair of Hyosung Dispenser For Nano Cash ** Includes Board! **	\$461.00		
	R723231-03	Repair of Hyosung or Tranax Dispenser Main Board	\$132.00		
	R72881227	Repair of Hyosung Note Separator Assembly, Drawer Style	\$128.00		
	R15111339-3	Repair of Tranax MCDU Multiple Cassette Dispenser	\$409.00		
	R15116001-1	Repair of Tranax MCDU Single Cassette Dispenser	\$262.00		
	R15111339-2	Repair of Tranax SCDU Single Cassette Dispenser	\$262.00		
	R15111339-1	Repair of Tranax TCDU Dispenser, 800 Note Fixed	\$251.00		
	Mainboard & Electronics	<b>R723366-05</b>	<b>Fix SRAM Failure or Fix NVRAM Failure on Hyosung / Tranax Mainboard</b>	<b>\$55.00</b>	
R728414-06		Repair of Hyosung / Tranax Mainboard For MBS5000 or MB2500CE	\$254.00		
R16111284-1		Repair of Hyosung / Tranax Nano Cash Mainboard	\$136.00		
R7470000009		Repair of Hyosung 1800 Main Board	\$153.00		
RS723366-03		Repair of Hyosung 1000/1500/2100 Mainboard Software Load/Flash Update	\$62.00		
R723366-03		Repair of Hyosung Mini-Bank 1000 / 1500 / 2100 Main Board	\$153.00		
R749000-05		Repair of Hyosung Mini-Bank 1000 / 1500 / 2100 Modem Main Board	\$104.00		
RS16110392-1		Repair of Tranax Mainboard For MB-1700 - Software Load Only	\$62.00		
RS16116006-1		Repair of Tranax Mainboard For MB-1700W - Software Load Only	\$62.00		
R16116003-1		Repair of Tranax Mainboard w/ Modem, 128MB For MBc4000 or MBe4000	\$419.00		
R16110272-1		Repair of Hantle / Tranax x4000 Main CE Assembly	\$262.00		
R7390000013		Repair of Hyosung 5000XP Mainboard Computer	\$524.00		

Manufacturer	Category	Product Model	Product Name	Price
	Power Supplies	R711304-01	Repair of Hyosung / Tranax Power Supplies (MB1000, 2XXX, 15XX, 18XX)	\$146.00
		R5621000002	Repair of Hyosung Power Supply For 5000XP, 5300XP, 5100, 5100T, 6200	\$263.00
		R5621000002	Repair of Hyosung / Tranax Nano Cash Power Supply	\$146.00
	Printers (SHU)	R723356-03	Repair of Hyosung / Tranax Printer Board For 1500	\$125.00
		R728656-10	Repair of Hyosung / Tranax / Hantle Printer Assembly, Excluding PCB Board	\$132.00
		R72323011	Repair of Hyosung / Tranax Printer Control Board	\$90.00
	Screens (LCD)	R01160-97027	Repair of Hyosung / Tranax 10.4" Color LCD	\$104.00
		R01160-96027	Repair of Hyosung / Tranax 5.7" Color LCD	\$83.00
		R728810-08	Repair of Hyosung / Tranax Mono LCD	\$83.00
		R5611000072	Repair of Hyosung 7" Color LCD Screen For NH-1800	\$104.00
		R72320201	Repair of Hyosung LCD Inverter Board, Mono	\$32.00
		R56001106	Repair of Hyosung 12.1" Color Touch Screen LCD For 5000XP	\$104.00

	Card Readers	R09600-00040	Repair of Triton Card Reader for 8100, 9100, 9600 or 9700	\$75.00
	Cassettes	R09005-00312	Repair of Triton TDM100 Cassette	\$50.00
		R09005-00313	Repair of Triton TDM150 Cassette	\$50.00
R09005-00314		Repair of Triton TDM150 or TDM250 Cassette, New Bill Pick Included	\$105.00	
Dispensers (CDU)	R09005-00005	Repair of Triton Mako Uninote Dispenser	\$304.00	
	R09005-00500	Repair of Triton TDM50 Dispenser & Cassette	\$241.00	
	R09005-01056	Repair of Triton TDM100 Dispenser & Cassette	\$230.00	
	R09005-01150	Repair of Triton TDM150 Dispenser & Cassette	\$237.00	
	R09005-00107	Repair of Triton TDM150 Dispenser w/ Bill Fish Extension & Cassette	\$262.00	
	R09015-00115	Repair of Triton TDM200 Dispenser & Cassette	\$356.00	
	R09005-01250	Repair of Triton TDM250 Dispenser & Cassette	\$367.00	
	R09005-00105	Repair of Triton TDM250 Dispenser w/ Bill Fish Extension & Cassette	\$419.00	
Keypads	R03016-00100	Repair of Triton 9100, 9700, 8100 Visa/PCI Keypad	\$104.00	
	R03016-00300	Repair of Triton 9600 or MAKO Visa Keypad	\$104.00	
	R03016-00017	Repair of VEPP Keypad Assembly SP-06-00-019 For RT2000, FT5000, RL5000	\$104.00	
Mainboard & Electronics	R06200-00013	Repair of Triton 9100 or 8100 Mainboard	\$120.00	
	R09600-02067	Repair of Triton 9600 External Modem / LCD Module, 256 Color	\$121.00	
	R09600-02001	Repair of Triton 9600 Mainboard	\$132.00	
	R09600-02004	Repair of Triton 9600 Memory Expansion Board 1 MB	\$121.00	
	R09600-02031	Repair of Triton 9600 Memory Expansion Board 2 MB	\$121.00	
	R09600-02002	Repair of Triton 9600 Memory Module, SS-2	\$132.00	
	R09600-00044	Repair of Triton 9600 Quad Port Board, EMV and Non EMV Compatible	\$121.00	
	R09600-02075	Repair of Triton 9600 SS-3 14,000 Baud Modem / LCD Module, Mono	\$230.00	
	R09600-02064	Repair of Triton 9600 SS-3 2400 Baud Modem / LCD Module, Color	\$293.00	
	R09600-02074	Repair of Triton 9600 SS-3 2400 Baud Modem / LCD Module, Mono	\$230.00	
	R09600-02076	Repair of Triton 9600 SS-3 33,600 Baud Modem / LCD Module, Mono	\$230.00	
	R09600-02066	Repair of Triton 9600 SS-3 33,600 Baud Modem / LCD Module, Color	\$293.00	
	R06200-00062	Repair of Triton 9700 Mainboard	\$120.00	
	R09100-00004	Repair of Triton Mako PCB Assembly Main Board Super Scrip, Color	\$157.00	
	R09100-00006	Repair of Triton Mako PCB Assembly Mako Main Monochrome	\$157.00	
	R09110-00077	Repair of Triton RL5000 Mainboard	\$342.00	
	R06200-00087	Repair of Triton RL5000 or FT5000 Docking Board PCB	\$83.00	
	R06200-00159	Repair of Triton RT2000 or RT5000 Docking Board PCB	\$83.00	
	R09005-00100	Repair of Triton TDM Dispenser Board, If Needed w/ Repair of Dispenser	\$105.00	
	R09200-00002	Repair of Triton X-scale Mainboard For RL2000, FT5000 or RT2000	\$304.00	
Power Supplies	R09110-00129	Repair of Triton 9100 Power Supply For Mini-Mech	\$136.00	
	R09110-00133	Repair of Triton 9100 Power Supply For TDM	\$136.00	
	R09110-01208	Repair of Triton 9100 Power Supply For TDM With Fan Assembly	\$157.00	

Manufacturer	Category	Product Model	Product Name	Price
	<b>Power Supplies (Cont)</b>	R08010-02000	Repair of Triton 9600 Power Supply	\$157.00
		R09700-00005	Repair of Triton 9700 Power Supply For SDD & NMD50	\$157.00
		R09700-00004	Repair of Triton 9700 Power Supply For TDM With Fan Assembly	\$157.00
		R09200-00109	Repair of Triton Power Supply	\$157.00
	<b>Printers (SHU)</b>	R06100-00021	Repair of Triton 9100, 9700 or Mako Printer with cutter	\$104.00
		R06200-00114	Repair of Triton 9100/8100/MAKO/RL/FT Printer Controller Board	\$73.00
		R09600-99541	Repair of Triton 9600 Printer with Cutter	\$237.00
		R01260-00013	Repair of Triton 9600 Series Printer Controller Board	\$184.00
		R06100-06045	Repair of Triton 9600 Series Printer w/Cutter & Control Board Assembly	\$419.00
		R06100-00039	Upgrade Old Triton RL5000 Printer Assy to Work With Latest Software	\$314.00
	<b>Screens (LCD)</b>	R01160-91027	Repair of Triton 9100/8100 Mono 5.7" LCD	\$83.00
		R01160-93027	Repair of Triton 9600 / 9700 / Mako Color 5.7" LCD	\$132.00
		R01160-92027	Repair of Triton 9600 / Mako Mono 5.7" LCD	\$83.00
R01160-94027		Repair of Triton FT5000 10.4" LCD	\$346.00	
R01160-95027		Repair of Triton RT2000/RL5000 10.4" Color LCD	\$346.00	



**Screens (LCD)**

RXTREMOLCD	Repair of Xtremo Series LCD	\$132.00
------------	-----------------------------	----------



**Power Supplies**

RPO200-415B	Repair of TBS Power Supply	\$136.00
-------------	----------------------------	----------

Ship All ATM Repairs To:  
**ATMPartMart.com**  
 Attn: Repair Department  
 733 Lakefield Road, Suite AA  
 Westlake Village, CA 91361

Please print out your email order confirmation and place it in the shipping box with the repair item(s).  
 Please also print your Order/RMA number on the outside of the shipping box.